

General Environmental Incident Summary

Incident: 2154 **Date/Time Notice:** 12/9/2013 1030 **DEM Incident No:**
Responsible Party: GES Power Rentals-Owner Kelly Farnsworth
Date Incident: 11/30/2013 **Time Incident:** **Duration:** 2 hours
County: Stark **Twp:** 139 **Rng:** 96 **Sec:** 2 **Qtr:**
Lat: 46.88206 **Long:** -102.75680 **Method:** Navigation quality GPS
Location Description: 1907 E I94 Business Loop
Dickinson, ND 58601
Lot behind the rear shop buildings
Submitted By: LeRoy Hendrickson **Affiliation:** Property Owner
Address: PO Box 162
City: Dickinson **State:** ND **Zip:** 58602

Received By:

Contact Person: Kelly Farnsworth
682 18th Ave West
Dickinson, ND 58601

Distance Nearest Occupied Building: 60 Feet

Type of Incident: Tank Leak

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 50.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Spill caused while moving tanks from one location to another

Risk Evaluation:

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved: Brad Torgerson with the Health Dept.

Updates

Date: 12/26/2013 **Status:** Reviewed - Follow-up Required

Author: Miller, Adam

Updated Volume:

Notes:

Spill is not located on an O&G location. Followup is necessary.

Date: 12/27/2013 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location 12/27/13 at 15:00. Weather conditions: mostly sunny, 42 F, 0-5 mph SW. Observed site and took photos. Spoke with representatives from the Dickinson Fire Department who had spoken to the property owner and the responsible party. Apparently, the responsible party had some sort of equipment sitting on the property which had leaked diesel fuel on to the soil surface before they moved the equipment to another location. The responsible party showed up to the location around 15:30 and explained to me that they had cleaned up the area where the fuel had been spilled by heating the soil and hand shoveling impacted soil into a barrel which was temporarily stored west of the location. Observations of the location showed that there might have been an area that appeared to have been impacted by diesel fuel. The ground was frozen, and a sample was collected from the 0- to 2-inch depth by chipping out soil with a spade and placing in a laboratory-supplied jar for transfer to the lab. Followup dependent upon lab results and observations in the spring when snow and piled snow does not cover the area.

Date: 12/27/2013 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Brad Torgerson from Waste Management Division is handling this situation by telephone. Please contact him before any on-site followup.

Date: 12/31/2013 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received an email from the Dickinson Fire Department Fire Chief with an attached letter that addressed GES Power Rentals and summarized the incident and required that GES document when, where, and what actions taken regarding the spill. Email and letter attached to file. Follow up with responsible party and Fire Department within the next month.

Date: 1/8/2014 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received a phone call from the Dickinson Fire Department Fire Chief 1/8/14 at 9:25 CT. Asked where we were in our process and wanted to be informed of status when lab results are received. Followup with Dickinson Fire Department and responsible party when lab results are provided.

Date: 1/9/2014 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Received a phone call from LeRoy Hendrickson at 4:30 CT, 1/8/14. Mr. Hendrickson was interested in knowing the status of our investigation of the site. I informed him that we are waiting for the lab results and relayed to him that, when the lab results are finished, we will contact him. Followup with Mr. Hendrickson and Dickinson Fire Department when lab results are completed.

Date: 8/29/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Volume:

Notes:

Arrived on location at 9:00 CT. 60 degrees F, rain, SW wind 10-20 mph. Observed the site and took photos. Used the GPS to determine sample location from December. Excavated soil from area inspected last December and tested for petroleum odors and staining. No odors or staining were noted. Follow up with landowner or responsible party to assess cleanup on location.